

Beaver-Camas Subbasin Assessment and Total Maximum Daily Loads



Department of Environmental Quality

May 3, 2005

Beaver-Camas Subbasin Assessment and TMDLs

May 3, 2005

**Prepared by:
Melissa Thompson
Idaho Falls Regional Office
Department of Environmental Quality
900 North Skyline, Suite B
Idaho Falls, Idaho 83402**

Acknowledgments

Gerald Messerli, Chairman of the Continental Divide Watershed Advisory Group, bestowed knowledge of the watershed and assisted with land access obtainment. Troy Saffle and of the DEQ-Idaho Falls Regional Office provided editorial reviews. Steve Robinson, Beneficial Use Reconnaissance Program (BURP) coordinator for the DEQ-Idaho Falls Regional Office, collected and supplied field data. Mark Shumar of DEQ-Technical Services provided a great deal of technical and field assistance. Dan Kotanski and Pat Koelsch, both of the Bureau of Land Management, provided water quality data, Proper Functioning Condition, and fisheries information. Lee Leffert, Brad Higginson, and Jim Capurso with the U.S. Forest Service (USFS) provided water quality, fisheries, and range management data for the subbasin. Jim Fredericks of Idaho Fish and Game (IDFG) supplied fish data.

Thank you all for contributing to the Beaver-Camas Subbasin Assessment and TMDL.

Cover photo provided by Idaho Department of Environmental Quality.

Table of Contents

Acknowledgments	i
Table of Contents	iii
List of Tables	vii
List of Figures	xi
List of Appendices	xv
Abbreviations, Acronyms, and Symbols	xvii
Executive Summary	xix
Subbasin at a Glance	xix
Key Findings	xxi
<i>Beaver Creek</i>	xxii
<i>Camas Creek</i>	xxiii
<i>Cow Creek</i>	xxiii
<i>Dairy Creek, East Fork Camas Creek, Modoc Creek, Threemile Creek, West Fork Camas Creek</i>	xxiii
1. Subbasin Assessment – Watershed Characterization	1
1.1 Introduction	1
Background	1
Idaho's Role	2
1.2 Physical and Biological Characteristics	3
Climate	3
<i>Air Temperature</i>	9
<i>Snow Water Content</i>	9
Subbasin Characteristics	11
<i>Setting and Topography</i>	11
<i>Geology</i>	13
<i>Soils</i>	15
<i>Vegetation</i>	25
<i>Hydrography/Hydrology</i>	27
<i>Fisheries</i>	28
<i>Beaver</i>	29
Subwatershed Characteristics	30
<i>Camas Creek National Refuge Subwatershed</i>	37
Stream Characteristics	39
1.3 Cultural Characteristics	47
Landuse	47
Land Ownership, Cultural Features, and Population	49
History and Economics	52

2. Subbasin Assessment – Water Quality Concerns and Status	53
2.1 Water Quality Limited Assessment Units Occurring in the Subbasin	53
About Assessment Units.....	53
Listed Waters.....	54
2.2 Applicable Water Quality Standards	54
Beneficial Uses	55
<i>Existing Uses</i>	55
<i>Designated Uses</i>	55
<i>Presumed Uses</i>	56
Criteria to Support Beneficial Uses.....	57
2.3 Pollutant/Beneficial Use Support Status Relationships.....	61
Temperature	61
Sediment.....	61
2.4 Summary and Analysis of Existing Water Quality Data	63
Flow Characteristics.....	63
Water Column Data	74
<i>Stream Temperature Data</i>	74
<i>Nutrient Data</i>	77
<i>Pathogen Data</i>	78
Biological and Other Data.....	79
<i>Surface Fines</i>	79
<i>Subsurface Fines</i>	79
<i>Streambank Assessments</i>	80
<i>Proper Functioning Condition</i>	81
<i>Fish Data</i>	84
<i>Solar Pathfinder</i>	87
Status of Beneficial Uses	95
Conclusions	95
2.5 Data Gaps.....	96
3. Subbasin Assessment–Pollutant Source Inventory	98
3.1 Sources of Pollutants of Concern	98
Point Sources	98
Nonpoint Sources	98
Pollutant Transport.....	98
3.2 Data Gaps.....	99
Point Sources	99
Nonpoint Sources	99
4. Subbasin Assessment – Summary of Past and Present Pollution Control Efforts.....	100
5. Total Maximum Daily Load(s)	102
5.1 In-stream Water Quality Targets.....	103
Design Conditions.....	105
<i>Sediment</i>	105
<i>Temperature</i>	105
Target Selection.....	108
<i>Sediment</i>	108
<i>Temperature</i>	108

Monitoring Points	113
<i>Subsurface Sediment</i>	113
<i>Streambank Stability</i>	114
<i>Temperature Monitoring</i>	114
5.2 Load Capacity	114
<i>Sediment</i>	114
<i>Temperature</i>	115
5.3 Estimates of Existing Pollutant Loads	115
<i>Sediment</i>	115
<i>Temperature</i>	115
5.4 Load Allocation	124
Wasteload Allocations.....	124
Load Allocations.....	124
<i>Sediment</i>	124
<i>Temperature</i>	124
Margin of Safety.....	125
Seasonal Variation.....	125
Background.....	126
Reserve.....	126
Construction Storm Water and TMDL Waste Load Allocations	126
<i>Construction Storm Water</i>	126
<i>The Construction General Permit (CGP)</i>	126
<i>Storm Water Pollution Prevention Plan (SWPPP)</i>	126
<i>Construction Storm Water Requirements</i>	127
Remaining Available Load	127
5.5 Implementation Strategies	127
Time Frame.....	127
Approach.....	128
Responsible Parties	128
Monitoring Strategy	128
5.6 Conclusions	128
References Cited	130
<i>GIS Coverages</i>	133
Glossary	134
Appendix A. Beneficial Use Reconnaissance Program Stream Data	154
Appendix B. Unit Conversion Chart	160
Appendix C. State and Site-Specific Standards and Criteria	164
Appendix D. Data Sources.....	172
Appendix E. Subsurface Fine Sampling Results.....	176

Appendix F. Streambank Erosion Inventory Method	180
Appendix G. Streambank Erosion Inventory Data Sheets	188
Appendix H. Potential Natural Vegetation for TMDLs	192
Appendix I. Aerial Photo Interpretation	196
Appendix J. Canopy Cover Estimates and Targets	200
Appendix K. Distribution List	210
Appendix L. Public Comments	212
Public Comments and Responses	212

List of Tables

Table A. Streams and pollutants for which TMDLs were developed.....	xx
Table B. Summary of assessment outcomes.....	xxiv
Table 1. Weather Stations located in the Beaver-Camas Subbasin.	4
Table 2. Period of record monthly climate summary for the Dubois weather station.	5
Table 3. Period of record monthly and annual climate summary for the Hamer weather station.....	6
Table 4. Period of record monthly and annual climate summary for the Kilgore Weather Station.	7
Table 5. Mean maximum daily air temperature data for two Agrimet Stations.....	9
Table 6. Beaver-Camas STATSGO Soil data Summary.....	17
Table 7. BLM identified rare plants in the Beaver-Camas Watershed.	25
Table 8. CDC list of special status plants located in Clark County.	27
Table 9. Land use statistics for the Beaver-Camas Subbasin.	47
Table 10. Landownership statistics for the Beaver-Camas Subbasin.....	49
Table 11. §303(d) Segments in the Beaver-Camas Subbasin.....	54
Table 12. Beaver-Camas Subbasin designated beneficial uses.....	56
Table 13. Beaver-Camas Subbasin presumed/existing beneficial uses	57
Table 14. Selected numeric criteria supportive of designated beneficial uses in Idaho water quality standards.	59
Table 15. USGS gauge station data.	63
Table 16. 2004 DEQ temperature data and number of days where water temperatures exceeded the cold water aquatic life criteria during the entire monitoring period.	75

Table 17. 2004 DEQ temperature data and number of days where water temperatures exceeded the salmonid spawning criteria during the entire monitoring period.	76
Table 18. 2000, 2001, 2002, and 2003 USFS Temperature data and number of days where water temperatures exceeded the cold water aquatic life criteria during the entire monitoring period.	76
Table 19. 2000, 2001, 2002, and 2003 USFS Temperature data and number of days where water temperatures exceeded the salmonid spawning criteria during the entire monitoring period.	77
Table 20. DEQ and BLM Nutrient Monitoring Data.	77
Table 21. DEQ McNeil Sediment Core sample sites and percentage of depth (4 in) fine sediment.	80
Table 22. Camas Creek Erosion Inventory Summary.....	81
Table 23. DEQ Fish Data Summary	84
Table 24. IDFG Fish Data Summary.....	85
Table 25. BLM Fish Data Summary.....	86
Table 26. USFS Fish Data Summary.....	87
Table 27. Percent annual and summer effective shade for stream sites in the Beaver-Camas Subbasin.....	89
Table 28. Beaver Creek Established Shade Target Values.....	110
Table 29. Camas Creek Established Shade Target Values.....	110
Table 30. Dairy Creek Established Shade Target Values.....	111
Table 31. Modoc Creek Established Shade Target Values	111
Table 32. Threemile Creek Established Shade Target Values	112
Table 33. East Camas Creek Established Shade Target Values	112
Table 34. West Camas Creek Established Shade Target Values	113

Table 35. Sediment load allocations for Beaver-Camas Subbasin.	124
Table 36. Temperature load allocations for Beaver-Camas Subbasin.....	125
Table 37. Summary of assessment outcomes.	129
Table B-1. Metric - English unit conversions.....	162
Table D-1. Data sources for Beaver-Camas Subbasin Assessment.	174
Table E-1. Beaver Creek McNeil Data	178
Table G-1. Camas Streambank Erosion Inventory Data Sheet	190
Table J-1. Beaver Creek Shade Estimates and Targets.....	202
Table J-2. Camas Creek Shade Estimates and Targets.....	203
Table J-3. Dairy Creek Shade Estimates and Targets.....	204
Table J-4. East Camas Creek Shade Estimates and Targets.....	204
Table J-5. Modoc Creek Shade Estimates and Targets.	205
Table J-6. Threemile Creek Shade Estimates and Targets.	206
Table J-7. West Camas Creek Shade Estimates and Targets.....	207

List of Figures

Figure 1. 30-Year Average Daily Temperature and Precipitation for Dubois Weather Station.	5
Figure 2. 30-Year Average Daily Temperature and Precipitation for Hamer Weather Station	6
Figure 3. 30-Year Average Daily Temperature and Precipitation for Kilgore Weather Station.	7
Figure 4. Beaver-Camas Subbasin Total Annual Precipitation and Weather Station Locations.	8
Figure 5. Snotel Graph for Period of Record at the Crab Creek Monitoring site.	10
Figure 6. Snotel Graph for 1983 through 1993 at the Island Park Monitoring Site.	10
Figure 7. Snotel Graph for the Period of 1994 through 2004 at the Island Park Monitoring Site.	11
Figure 8. Beaver-Camas Subbasin Geology	14
Figure 9. STATSGO Soil Map Unit Identifications.	16
Figure 10. Soil Units on Soil Erosion Potential.	19
Figure 11. Soil Units on Slope.	20
Figure 12. Soil Units on Soil Thickness.	21
Figure 13. Soil Units on Soil Permeability.	22
Figure 14. Soil Units on Hydrologic Characteristics of Soil.	23
Figure 15. Soil Units on Soil Drainage.	24
Figure 16. Beaver-Camas Subbasin Landcover.	26
Figure 17. Beaver-Camas Subbasin Subwatershed Boundaries.	31
Figure 18. Drainages in the Upper Beaver Creek Subwatershed.	34
Figure 19. Drainages in the Lower Beaver Creek Subwatershed.	34
Figure 20. Drainages in the Spring Creek Subwatershed.	36
Figure 21. Camas Creek Subwatershed.	37
Figure 22. Camas Creek National Refuge Subwatershed.	38
Figure 23. Cottonwood Creek Subwatershed.	39
Figure 24. Stream and BURP Site Locations in the Upper Beaver Creek Subwatershed.	41
Figure 25. Stream and BURP Site Locations in the Lower Beaver Creek Subwatershed.	42
Figure 26. Stream and BURP Site Locations in the Spring Creek Subwatershed.	43
Figure 27. Stream and BURP Site Locations in the Camas Creek Subwatershed.	44
Figure 28. Stream and BURP Site Locations in the Camas Creek, National Wildlife Subwatershed.	45
Figure 29. Stream and BURP Site Locations in the Cottonwood Creek Subwatershed.	46

Figure 30. Land Use in the Beaver-Camas Subbasin.....	48
Figure 31. Landownership and Cultural Features of the Beaver-Camas Subbasin.	50
Figure 32. USGS Gauge Station Locations.	65
Figure 33. Peak Streamflow (cfs) for station# 1310900, Camas Creek near Kilgore, ID (1921-1930).....	66
Figure 34. Daily Mean Streamflow (cfs) for Station #13108500, Camas Creek near Kilgore, ID (1921-1930).	66
Figure 35. Peak Streamflow (cfs) for Station #13108500, Camas Creek at 18 mile Shearing Corral near Kilgore, ID (1937-1973).....	67
Figure 36. Daily Mean Streamflow (cfs) for Station #13108500, Camas Creek at 18 mile Shearing Corral near Kilgore, ID (1937-1973).	67
Figure 37. Peak Streamflow (cfs) for Station #1308900, Camas Creek at Red Road Near Kilgore (1985-1991).	68
Figure 38. Daily Mean Streamflow (cfs) for Station #1308900, Camas Creek at Red Road Near Kilgore (1985-1991).....	68
Figure 39. Peak Streamflow (cfs) for Station #1308900, Camas Creek Near Camas, ID (1921-1926).....	69
Figure 40. Daily Mean Streamflow (cfs) for Station #1308900, Camas Creek Near Camas, ID (1921-1926).	69
Figure 41. Peak Streamflow (cfs) for Station #13112000, Camas Creek at Camas, ID (1925- 2003).....	70
Figure 42. Daily Mean Streamflow (cfs) for Station #13112000, Camas Creek at Camas, ID (1925-2003).....	70
Figure 43. Peak Streamflow (cfs) for Station #13113000, Beaver Creek at Spencer (1940- 1993).....	71
Figure 44. Daily Mean Streamflow (cfs) for Station #13113000, Beaver Creek at Spencer (1940-1993).....	72
Figure 45. Peak Streamflow (cfs) for Station #13113500, Beaver Creek at Dubois (1921- 1987).....	72
Figure 46. Daily Mean Streamflow (cfs) for Station #13113500, Beaver Creek at Dubois (1921-1987).....	73
Figure 47. Peak Streamflow (cfs) for Station #13114000, Beaver Creek at Dubois (1921- 1991).	73
Figure 48. Daily Mean Streamflow (cfs) for Station #13114000, Beaver Creek at Dubois (1921-1991).....	74
Figure 49. BLM Proper Functioning Conditioning Results for Beaver Creek near Headwaters.	82
Figure 50. BLM Proper Functioning Conditioning Results for Beaver Creek below Flat Creek Confluence.	83
Figure 51. Modoc Creek Solar Pathfinder Sites.....	89

Figure 52. Miners Creek Solar Pathfinder Sites.....	90
Figure 53. Threemile Creek Solar Pathfinder Sites.....	90
Figure 54. Upper Beaver, and Dairy Creek Solar Pathfinder Sites.	91
Figure 55. Beaver Creek Solar Pathfinder Sites (B26-B33).....	91
Figure 56. Beaver Creek Solar Pathfinder Sites (B26-33).	92
Figure 57. Beaver Creek Solar Pathfinder Sites (B9-25).	92
Figure 58. Camas Creek Solar Pathfinder Sites (C1-C8).	93
Figure 59. Camas Creek Solar Pathfinder Sites (C9-C13).	93
Figure 60. Camas Creek Solar Pathfinder Sites (C14-C22).	94
Figure 61. Camas Creek Solar Pathfinder Sites (C24-C27).	94
Figure 62. Estimated Percent Canopy Cover for Beaver Creek	117
Figure 63. Estimated Percent Canopy Cover for Camas Creek	118
Figure 64. Estimated Percent Canopy Cover for Dairy Creek	119
Figure 65. Estimated Percent Canopy Cover for East Camas Creek	120
Figure 66. Estimated Percent Canopy Cover for Modoc Creek	121
Figure 67. Estimated Percent Canopy Cover for Threemile Creek.....	122
Figure 68. Estimated Percent Canopy Cover for West Camas Creek	123

List of Appendices

Appendix A. Beneficial Use Reconnaissance Program Stream Data	154
Appendix B. Unit Conversion Chart	160
Appendix C. State and Site-Specific Standards and Criteria	164
Appendix D. Data Sources.....	172
Appendix E. Subsurface Fine Sampling Results.....	176
Appendix F. Streambank Erosion Inventory Method.....	180
Appendix G. Streambank Erosion Inventory Data Sheets	188
Appendix H. Potential Natural Vegetation for TMDLs	192
Appendix I. Aerial Photo Interpretation	196
Appendix J. Canopy Cover Estimates and Targets	200
Appendix K. Distribution List	210
Appendix L. Public Comments	212

Abbreviations, Acronyms, and Symbols

§303(d)	Refers to section 303 subsection (d) of the Clean Water Act, or a list of impaired water bodies required by this section	CWE	cumulative watershed effects
μ	micro, one-one thousandth	DEQ	Department of Environmental Quality
§	Section (usually a section of federal or state rules or statutes)	DO	dissolved oxygen
ADB	assessment database	DOI	U.S. Department of the Interior
AU	assessment unit	DWS	domestic water supply
AWS	agricultural water supply	EPA	United States Environmental Protection Agency
BLM	United States Bureau of Land Management	ESA	Endangered Species Act
BMP	best management practice	F	Fahrenheit
BOR	United States Bureau of Reclamation	FWS	U.S. Fish and Wildlife Service
BURP	Beneficial Use Reconnaissance Program	GIS	Geographical Information Systems
C	Celsius	HUC	Hydrologic Unit Code
CFR	Code of Federal Regulations (refers to citations in the federal administrative rules)	I.C.	Idaho Code
cfs	cubic feet per second	IDAPA	Refers to citations of Idaho administrative rules
cm	centimeters	IDFG	Idaho Department of Fish and Game
CWA	Clean Water Act	IDL	Idaho Department of Lands
CWAL	cold water aquatic life	km	kilometer
		km²	square kilometer
		LA	load allocation
		LC	load capacity
		m	meter

m³	cubic meter	TMDL	total maximum daily load
mi	mile	TP	total phosphorus
mi²	square miles	TS	total solids
MGD	million gallons per day	TSS	total suspended solids
mg/L	milligrams per liter	t/y	tons per year
mm	millimeter	U.S.	United States
MOS	margin of safety	U.S.C.	United States Code
NA	not assessed	USDA	United States Department of Agriculture
NB	natural background	USDI	United States Department of the Interior
NPDES	National Pollutant Discharge Elimination System	USFS	United States Forest Service
NRCS	Natural Resources Conservation Service	USGS	United States Geological Survey
NTU	nephelometric turbidity unit	WAG	Watershed Advisory Group
PCR	primary contact recreation	WBAG	<i>Water Body Assessment Guidance</i>
PFC	proper functioning condition	WBID	water body identification number
ppm	part(s) per million	WLA	wasteload allocation
QA	quality assurance	WQLS	water quality limited segment
QC	quality control	WQMP	water quality management plan
SBA	subbasin assessment	WQS	water quality standard
SCR	secondary contact recreation		
SS	salmonid spawning		
STATSGO	State Soil Geographic Database		
TKN	total Kjeldahl nitrogen		

Executive Summary

The federal Clean Water Act (CWA) requires that states and tribes restore and maintain the chemical, physical, and *biological integrity* of the nation's waters. States and tribes, pursuant to Section 303 of the CWA, are to adopt water quality standards necessary to protect fish, shellfish, and wildlife while providing for recreation in and on the nation's waters whenever possible. Section 303(d) of the CWA establishes requirements for states and tribes to identify and prioritize water bodies that are *water quality limited* (i.e., water bodies that do not meet water quality standards). States and tribes must periodically publish a priority list (a "§303(d) list") of impaired waters. Currently this list must be published every two years. For waters identified on this list, states and tribes must develop a total maximum daily load (TMDL) for the pollutants, set at a level to achieve water quality standards.

This document addresses the water bodies in the Beaver-Camas Subbasin that have been placed on Idaho's current §303(d) list.

This *subbasin assessment* (SBA) and TMDL analysis have been developed to comply with Idaho's TMDL schedule. The assessment describes the physical, biological, and cultural setting; water quality status; pollutant sources; and recent pollution control actions in the Beaver-Camas Subbasin, located in southeastern Idaho.

The first part of this document, the SBA, is an important first step in leading to the TMDL. The starting point for this assessment was Idaho's current §303(d) list of water quality limited water bodies. Six segments of the Beaver-Camas Subbasin were listed on this list. The SBA examines the current status of §303(d) listed waters and defines the extent of impairment and causes of water quality limitation throughout the subbasin. The TMDL analysis quantifies pollutant sources and allocates responsibility for load reductions needed to return listed waters to a condition of meeting water quality standards.

Subbasin at a Glance

The Beaver-Camas Subbasin of southeastern Idaho (Figure A) is a watershed of the Upper Snake River Basin. This watershed is the easternmost in a series of five sinks drainages in the Upper Snake River Basin. The hydrology of the subbasin is dominated by both natural and human caused flow alterations, which contribute to limited beneficial use attainment in several 303(d) listed *reaches* in the watershed.

Data has been collected and analyzed to evaluate the scope of the water quality limiting issues on the 303(d) listed and non-listed streams in the Beaver-Camas Subbasin Creek Subbasin. Seven temperature TMDLs and one sediment TMDL, as summarized in Table A, have been developed from the results of the data, or in response to the data.

Table A. Streams and pollutants for which TMDLs were developed.

Stream	Pollutant(s)
Beaver Creek	Temperature
Camas Creek	Sediment, Temperature
Dairy Creek	Temperature
East Camas Creek	Temperature
Modoc Creek	Temperature
Threemile Creek	Temperature
West Camas Creek	Temperature

TMDLs for sediment are quantified through streambank erosion inventories. Sediment loading targets were developed based on literature detailing expected natural conditions and substrate sediment impacts on salmonid spawning. The target values established will be used to quantify streambank recovery and determine the need for additional management practices to improve water quality.

TMDL targets for substrate sediment are adopted from literature detailing its impact on salmonid egg and fry emergence. The target values established in this assessment will be used to indicate trends related to channel morphology and streambank recovery. Beneficial use support status and compliance with state water quality standards will be used to determine the need for additional best management practices to improve water quality.

Temperature TMDLs have been developed for all streams, where thermograph data has been collected, to support salmonid spawning and cold water aquatic life. Cold water aquatic life and salmonid spawning have been determined to be the presumed uses for all streams in the subbasin.

Reduced riparian vegetation contributes to accelerated streambank erosion, which results in increased thermal loading, which, combined with associated changes in channel morphology are the primary causes of increased temperature loading in affected streams. Elevated temperatures from reduced riparian vegetation and accelerated streambank erosion have been exacerbated by an ongoing drought in the subbasin.

TMDLs were not developed for streams listed as flow altered. Streams listed as flow altered and streams discovered to be flow altered for significant portions of the year do not have a reasonable potential to support beneficial uses. The EPA does not believe that flow (or lack of flow) is a pollutant as defined by CWA Section 502(6). Since TMDLs are not required to be established for waterbodies impaired by pollution but not pollutants, TMDLs will not be developed for flow altered streams, at this time. They will be relisted as flow altered in subsequent integrated reporting events.




Figure A. Beaver-Camas Subbasin at a Glance

Key Findings

The hydrology of the Beaver-Camas subbasin is relatively complex, with a combination of gaining reaches in the upper elevations and losing reaches in the lower elevations.

Hydrograph data show that a peak in flow is experienced in the early spring, when spring *runoff* peaks and surface water is able to reach the lower sections of the subbasin. Natural runoff flows are seen in the lower section of the subbasin for a short period of time during the peak runoff event. Natural infiltration into the basalt streambed is the causative agent for the absence of lower watershed flows. This is the natural hydrologic behavior of surface waters in the subbasin.

Land use in the subbasin is essentially split into two sections; the upper half of the subbasin is used for rangeland, and the lower section of the subbasin is utilized for crop production. The demand for surface water in the lower half of the subbasin is very high, therefore a

complex system of irrigation canals have been developed for the transport of water. Since surface water is naturally infiltrating out of the stream, groundwater must be returned to Camas Creek to provide the necessary water for irrigation.

Since the lower sections of Beaver and Camas Creeks (303(d) listed) are naturally dry and have been converted into canal systems, TMDLs will not be developed for these listed sections.

Hydrology in the upper half of the subbasin is, for the most part, different than that of the lower half. Perennial flows are sustained in the majority of the streams and land management is focused towards rangeland grazing.

Riparian grazing is the principal source of temperature and sediment loading to the watershed. Riparian destruction leads to overall changes in channel morphology, sedimentation, and reduced stream shading, which leads to increased solar loading to the stream.

TMDLS are recommended for sediment and temperature impaired streams based upon the following criteria:

Temperature TMDLs have been developed for streams where temperature data has been collected and shows an exceedance of temperature criteria in greater than 10% of observation days during spring or fall spawning periods. Thermograph data established that temperature TMDLs were necessary to meet the numeric salmonid spawning criteria [IDAPA 58.01.02.250(02)]. All Temperature TMDL load reductions were developed by quantifying the solar radiation through solar pathfinder data, which measures the percent solar time. Percent solar time was converted into a solar load by multiplying the percent of solar time (April through September) by an average solar load in kWh/m²/day. Streambank erosion, reduced riparian vegetation, and low flow conditions are the causes of increased water temperatures in the subbasin. The TMDL temperature targets are the salmonid spawning temperature criteria established in Idaho's administrative code [IDAPA 58.01.02.250(02)].

There are five 303(d) listed stream segments in the Beaver-Camas Subbasin and seven TMDLs established for streams in the subbasin. Some TMDLs have been established for non-listed streams since water quality data show that there is an exceedance of Idaho's water quality standards. Table B provides a summary of the assessment outcomes for each of the 303(d) listed segments and the unlisted segments receiving a TMDL.

Beaver Creek

There are two 303(d) listed segments on Beaver Creek. The listed segments are from Spencer to Dubois and from Dubois to Camas Creek. Pollutants for both of the listed segments are flow alteration, habitat alteration, nutrients, sediment, and temperature. Stream temperature data collected in and above Spencer show that temperatures exceed Idaho's numeric standard. Because of this, a temperature TMDL was established for Beaver Creek from Modoc Creek to I-15 Exit 172. Exit 172 is the endpoint for the TMDL since perennial flows are seldom seen below this point.

Water quality data show that sediment and nutrients are not definitively the sources of beneficial use impairment in the listed segment of Beaver Creek. Beaver Creek from Exit 172 to Camas Creek (mouth) is naturally devoid of flow, so it is proposed to be de-listed and re-listed as flow altered.

Camas Creek

Camas Creek is 303(d) listed from headwaters (Spring Creek confluence) to mouth. The listed pollutants for the upper segment of Camas Creek are flow alteration, nutrients, and sediment. Part of this section, above T9N, R37E, Section 16 (N44.19270°, W-111.98284°), is perennial. The lower half of this segment is flow altered (irrigation) and natural infiltration into the basalt stream bed is extensive as well. Riparian grazing has contributed to bank erosion and elevated stream temperatures. Sediment and temperature TMDLs have been calculated to address the pollutants of concern above T9N, R37E, Section 16.

The lower section of Camas Creek is 303(d) listed for flow alteration, habitat alteration, sediment, nutrients, and temperature. This section of Camas Creek is intermittent and flow altered for irrigation, therefore this segment should be de-listed for sediment, nutrients, and temperature and re-listed as flow altered.

Cow Creek

Cow Creek is 303(d) listed for an unknown pollutant. Cow Creek is an ephemeral stream and therefore should be de-listed for unknown pollutants. Ephemeral streams are not expected to support the same biological communities as perennial waters.

Dairy Creek, East Fork Camas Creek, Modoc Creek, Threemile Creek, West Fork Camas Creek

Dairy, East Fork Camas, Modoc, Threemile, and West Fork Camas Creeks are all streams that are not 303(d) listed. However, stream temperature data, collected on all five streams, showed that there were major exceedances in Idaho's numeric temperature criteria. Temperature TMDLs were established for all five streams.

Land management and land use in all of the streams is homogeneous with riparian grazing impacting overall stream health and water quality.

Table B. Summary of assessment outcomes.

Water Body Segment [WQLS]	Assessment unit of 17040214	Pollutant	TMDL(s) Completed	Recommended Changes to §303(d) List	Justification
Beaver Creek* (Spencer to Dubois) [2194]	SK015_05	Flow	No	List below Exit 172 and de-list above Exit 172	Flow Altered (natural)
		Habitat	No	None	EPA Policy
		Nutrients	No	De-list	No Exceedances Documented
		Sediment	No	De-list	No Impacts Documented
		Temperature	Yes	None	Exceedances Documented
Beaver Creek* (Dubois to Camas Creek) [2193]	SK003_05 SK014_05	Flow	No	None	Flow Altered (natural and anthropogenic)
		Habitat	No	None	EPA Policy
		Nutrients	No	None	Flow Altered (natural and anthropogenic)
		Sediment	No	None	Flow Altered (natural and anthropogenic)
		Temperature	No	None	Flow Altered (natural and anthropogenic)
Beaver Creek (Headwaters to Spencer)	SK021_02 SK021_03 SK020_03 SK018_04 SK024_02	Temperature	Yes	None	Exceedances Documented
Camas Creek* (Spring Creek to Hwy 91) [2191]	SK002_05	Flow	No	List below T9N, R37E, Section 16 and de-list above	EPA Policy
		Habitat	No	None	EPA Policy
		Nutrients	No	De-list	No Exceedances Documented
		Sediment	Yes	None	Impacts Documented
		Temperature	Yes	None	Impacts Documented
Camas Creek* (Hwy 91 to Mud Lake) [2190]	SK001_06	Flow	No	None	Flow Altered (natural and anthropogenic)
		Nutrients	No	De-list	Flow Altered (natural and anthropogenic)
		Sediment	No	De-list	Flow Altered (natural and anthropogenic)
Cow Creek* (Headwaters to Thunder Gulch) [5233]	SK018_04	Unknown	No	De-list	Flow Altered (natural)
Dairy Creek (Headwaters to Mouth)	SK018_02	Temperature	Yes	None	Exceedances Documented
East Camas Creek (Headwaters to Mouth)	SK011_03 SK010_02 SK010_03	Temperature	Yes	None	Exceedances Documented
Modoc Creek (Headwaters to Mouth)	SK021_02	Temperature	Yes	None	Exceedances Documented
Threemile Creek (Headwaters to Mouth)	SK017_02 SK017_03	Temperature	Yes	None	Exceedances Documented
West Camas Creek (Headwaters to Mouth)	SK012_03 SK013_02 SK013_03	Temperature	Yes	None	Exceedances Documented

*1998 303(d) listed segment